


Checking Out a Skid

1 Enter the Action Target Enterprise Portal.


ms: [redacted] environment: [redacted] site: [redacted] related to the [redacted] environment.

Employee Directory			Status	Message Center	Browser Support
<input type="text" value="Employee Name"/>			<ul style="list-style-type: none">Data WarehouseEmail / Office 365ERP Legacy AppsERP Web AppsInternet		<p>Preferred: Microsoft Edge Supported: Mozilla Firefox 4, Google Chrome Limited: Microsoft Internet Explorer 9 1 Does not support launching ECH Manager or Single 2 Does not support launching ECH Manager</p>
Employee Name	Phone Number	Actions			

2 Click on the "Supply Chain" menu located near the top of the portal.



3 Click on the "Shop Tracker" option from the drop-down menu.



4 Click on the "Material" tab near the top of the tool.

Shop Tracker

Schedule Setup Time **Material** Staging

Schedule

Operator Actions: Check In, Check Out, Documents, Fulfill, EHR, Labels, Add Destination, Close Job, QC

Search: Queued, Kitting, **Staged**, In-Process, Parts in Batch, Work Order

Priority	WO ID	MTR	Req Qty	Part Number	Description	Operation	WO Notes	Start	Status	Batch ID	Mat Available	Next Op Name	WO Due
5		jb-1055-1	1	49135	(Phase-Out - R	elec-asmemb	Inspect Repc	2025-03-07	staged		true		
6	58793	mo-170454	4	33785	-REDLINE- Aut	elec-asmemb	Indonesia 2C	2025-03-27	in-process	14637	false		2025-05-12
6	58794	mo-170454	4	33785	-REDLINE- Aut	elec-asmemb	Indonesia 2C	2025-03-27	in-process	14637	false		2025-05-12
6	58695	mo-170270	15	33785	-REDLINE- Aut	elec-asmemb	Indonesia 2C	2025-03-27	in-process	14636	true		2025-04-28
6	58697	mo-170270	4	33785	-REDLINE- Aut	elec-asmemb	Indonesia 2C	2025-03-27	in-process	14636	false		2025-04-28
6	59693	mo-172027	1	33785	-REDLINE- Aut	elec-asmemb	WAR Ord 15	2025-03-27	in-process	14637	true		2025-05-19
6	58899	mo-170628	15	33785	-REDLINE- Aut	elec-asmemb	Israel-IMI 15	2025-03-27	in-process	14637	false		2025-05-16
6	58702	mo-170288	16	33785	-REDLINE- Aut	elec-asmemb	Indonesia 2C	2025-03-27	in-process	14636	false		2025-05-12

5 Select your desired skid you want to check out.

Shop Tracker

Schedule Setup Time **Material** Staging

Select an MO in Main Tab: Check Out, Remnant

Content Skids

No data loaded

MO	3125	4529	1516	3055	1348	2023
A1e	0-1-0	0-1-1	0-1-2	1-1-0	1-1-1	1-1-2
	3127	3936		4067	2971	
	0-0-0	0-0-1	0-0-2	1-0-0	1-0-1	1-0-2
B1c	2433	1484		4620	3175	4046
	0-1-0	0-1-1		1-1-0	1-1-1	1-1-2
	3396	4453		3000	2923	1444
	0-0-0	0-0-1	0-0-2	1-0-0	1-0-1	1-0-2
IM0c		4511	4311	4311	4529	3125
	0-0-0	0-0-1	0-0-2	0-0-3	0-0-4	0-0-5
					0-0-6	0-0-7
						0-0-8
IM1c			4163	4163	4242	
	0-0-4	0-0-3	0-0-2	0-0-1	0-0-0	

119 - Electronics Flammables Cabinet



NOTE: When you check a skid out it also erases all of its inventory content records. Make sure you are okay with this before confirming the check out. If inventory is still present on the skid this could cause serious inventory issues in the future.

6 Click the "Check Skid Out" option from the menu.

Shop Tracker

Schedule Setup Time **Material** Staging Work Cell: pi

Select an MO in Main Tab Check Out Remnant

Content Skids

No data loaded

A0a	1695	3243			A0d				A0f			A0g		1557	4641
	0-0-3	0-0-2	0-0-1	0-0-0		0-1-2	0-1-1	0-1-0		0-0-1	0-0-0		0-1-2	0-1-1	0-1-0
							0-0-2	0-0-1	0-0-0				1032		
													0-0-2	0-0-1	0-0-0

A1e

	3125	4529	1516	3055	1348	2023			
	0-1-0	0-1-1	0-1-2						
		3127	3936						
	0-0-0	0-0-1	0-0-2						

B1c

	2433	1484							
	0-1-0	0-1-1	0-1-2						
	3396	4453							
	0-0-0	0-0-1	0-0-2						

M0c

		4511	4311	4311	4529	3125			
	0-0-0	0-0-1	0-0-2	0-0-3	0-0-4	0-0-5	0-0-6	0-0-7	0-0-8

M1c

			4163	4163	4242				
	0-0-4	0-0-3	0-0-2	0-0-1	0-0-0				

119 - Electronics Flammables Cabinet

Search Edit Edit Skid Show Skids Clear Selection Transfer Refresh

Locations with Part Search Multi Selection Actions Transfer

Search: Skid Part Ponum Shop Job Search

Search: Location ID Part Search

Check Skid Out

- Store Skid
- Check Skid Out
- Load Skid
- Preview Contents

7

The skid has now been removed from the system.

This is a test environment. All changes are isolated to the testing environment.

Tracker

le Setup Time **Material** Staging Work Cell: pi34 - Electr

an MO in Main Tab Check Out Remnant

Content Skids
No data loaded

A0a	1695 0-0-3	3243 0-0-2			A0d				A0f			A0g		1557 0-1-2	4641 0-1-1
						0-1-2	0-1-1	0-1-0		0-0-1	0-0-0		1032 0-0-2		
						0-0-2	0-0-1	0-0-0							
A1e	3125 0-1-0	4529 0-1-1	1516 0-1-2		1348 1-1-0			2023 1-1-2							
		3127 0-0-0	3936 0-0-1		4067 1-0-0			2971 1-0-2							
B1c	2433 0-1-0	1484 0-1-1		4620 0-1-2	3175 1-1-0	4046 1-1-1									
		3396 0-0-0	4453 0-0-1		3000 0-0-2	2923 1-0-0	1444 1-0-1								
M0c		4511 0-0-0	4311 0-0-1	4311 0-0-2		4529 0-0-3	3125 0-0-4								
M1c			4163 0-0-4	4163 0-0-3	4242 0-0-2										

119 - Electronics Flammables Cabinet

Search Edit Edit Skid Show Skids Clear Selection Transfer Refresh

Locations with Part Search Multi Selection Actions Transfer

Search: Skid Part Ponum Shop Job Search

Search: Location ID Part Search